


# UPDATE 5TH NOV 2007

NOTE BC327's (6) are shown REVERSED on this overlay!

Add LINKS as below for correct Grounding.

"R2x" FIT A 100 ohm LEADED RESISTOR FROM "SPARE" TO JK1 PIN 1



5th Nov 07: LINK Pin 19 to pin 8 of PIC socket with a piece of resistor lead.

